

RENOVATION OF PITTED TANK BOTTOMS**glassmat reinforced solvent free phenolic epoxy coating system****4145**

a two page issue

September 2005
revision of 1-1999**SPECIFICATION 1**

glassmat reinforced solvent free epoxy coating system resistant to crude oil (up to 90°C/140°F), aliphatic hydrocarbons, leaded and unleaded gasoline and aviation fuels
for additional information see Sigma TankSelect

pretreatment

steel; blast cleaned to ISO-Sa2½ (SSPC-SP10)
blasting profile; 50-100 µm (2.0-4.0 mils)

paint system

primer (see item 2)

SigmaGuard 260

75 µm (3.0 mils)

pitfilling (see item 3) optional

Sigma NovaGuard 840

levelling of lap joints (see item 4)

Sigma NovaGuard 830

coving of corners (see item 4) optional

Sigma NovaGuard 830

coating + laminate (see item 5 and 6)

Sigma NovaGuard 840 (Clear) +
Non-woven glassmat

1200 µm (48,0 mils)
450 gr/m² (1,5 oz/ft²)

coating (see item 7)

Sigma NovaGuard 840 (Clear)

400 µm (16.0 mils)

optional layer (see items 8 and 9)

Sigma NovaGuard 840 (Clear) +
Non-woven glassmat +
Sigma NovaGuard 840 (Clear) *

400 µm (16.0 mils)
450 gr/m² (1,5 oz/ft²)
400 µm (16.0 mils)

coating (see item 10)

Sigma NovaGuard 840

400 µm (16.0 mils)

* if needed to improve wetting of the mat

Coating procedure

1. For blasting and coating guidelines: see sheet 4139.
2. Application of primecoat of SigmaGuard 260 - dft 75 µm/3.0 mils.
3. Before starting the final coating the substrate should be inspected for hidden steel defects. If necessary adequate repairs should be carried out.
4. Pitting can be filled by using a scrape layer of Sigma NovaGuard 840 (see sheet 4139).
5. For incomplete welded areas in the chine transition, striker plate bedding and lap joints etc., levelling is accomplished by trowel application using Sigma NovaGuard 830.



RENOVATION OF PITTED TANK BOTTOMS

glassmat reinforced solvent free phenolic epoxy coating system

4145

September 2005

6. "Stripe coat" of the prepared sharp edges and welding seams with Sigma NovaGuard 840. Apply the next full coat of Sigma NovaGuard 840 wet on wet or after appropriate cure.
7. Application of first coat of Sigma NovaGuard 840 (Clear) - dft 500 µm (20.0 mils)
8. Apply within an appropriate time non-woven glassmat 450 g/m² (1.5 oz/ft²). The non-woven glassmat should be brought into intensive contact with the liquid epoxy material using washer rollers and ribbed rollers. The surface should be smooth and free from air inclusions.
9. Application of 2nd coat Sigma NovaGuard 840 (Clear) - dft 400-500 µm (16.0-20.0 mils) as required to thoroughly wet out the glassmat.
10. Optional second layer of dft 400-500 µm (16.0-20.0 mils) Sigma NovaGuard 840 (Clear) followed by a second layer of non-woven glassmat.
11. Optional (if optional item 8 is used) coat Sigma NovaGuard 840 (Clear) - dft 400-500 µm (16.0-20.0 mils).
12. Application of one coat of Sigma NovaGuard 840 - dft 400 µm (16.0 mils).
13. The dried film, a minimum of 600 µm/24,0 mils has to be tested for the presence of pores, and repaired, where necessary, with Sigma NovaGuard 840 (see also 5). See also 2.7.10 of the working procedure.

Note:

The coats on the side shells must be applied step-wise in such a way that the system thickness gradually decreases up the vertical sides.

REFERENCES

Sigma NovaGuard 830	see product data sheet 7945
Sigma NovaGuard 840	see product data sheet 7468
SigmaGuard 260	see product data sheet 7944
Safe working in confined spaces	see information sheet 1433
Directives for ventilation practice	see information sheet 1434
Cleaning of steel and removal of rust	see information sheet 1490
Working procedures - general guidelines	see information sheet 4139

Limitation of Liability - The information in this data sheet is based upon laboratory tests we believe to be accurate and is intended for guidance only. All recommendations or suggestions relating to the use of the products made by Sigma Coatings, whether in technical documentation, or in response to a specific enquiry, or otherwise, are based on data which to the best of our knowledge are reliable. The products and information are designed for users having the requisite knowledge and industrial skills and it is the end-user's responsibility to determine the suitability of the product for its intended use.

Sigma Coatings has no control over either the quality or condition of the substrate, or the many factors affecting the use and application of the product. Sigma Coatings does therefore not accept any liability arising from loss, injury or damage resulting from such use or the contents of this data sheet (unless there are written agreements stating otherwise).

The data contained herein are liable to modification as a result of practical experience and continuous product development. This data sheet replaces and annuls all previous issues and it is therefore the user's responsibility to ensure that this sheet is current prior to using the product.

